

6 Series Indoor Station for CVBS Door Bell Firmware V2.2.4_build230213 Release Note (2023-02-20)

Device Model	DS-KH6320-TDE1, DS-KH6320-WTDE1, DS-KIS302-P
Firmware Version	V2.2.4_build230213
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

New Features


1. Support calling from analog doorbell (DS-KB2411T/2421T series) to indoor station and 5 indoor extensions at the same time.
Note: Android indoor station KH9310/9510/9310(B)/9510(B) do not support work as indoor extension of KH6320-WTDE1 and KH6320-TDE1.
2. Support live view, intercom and unlock analog doorbell from indoor extension.

Modified Features

1. Update ezvizsdk version to V2.15.1 and optimized the call forwarding time between indoor station and hik-connect server.

Compatibility and Restriction

1. The analog doorbell and sub doorphone share the capacity quantity. You can add maximum 1 doorphone + 14 sub doorphone + 2 analog doorbell to one indoor station. (if no analog doorbell, you can add 1 doorphone + 16 sub doorphone to one indoor station)
2. You can live view the analog doorbell from live view page




3. If main indoor station use V2.2.4 or later firmware, and indoor extension use firmware

earlier than V2.2.4, they will be some restriction:

Note: for better user experience and compatibility, we strongly recommend to update both main indoor station and extension to latest version firmware.

- a. indoor extension can only live view doorphone1 and can't live view doorphone2. So it's better to use both indoor station and extension with same model and firmware.
- b. Indoor extension can only unlock doorphone1 and not support enable intercom in live view page
- c. Not support live view analog doorbell in Hik-Connect app and indoor extension at the same time
- d. When calling from analog doorbell (no matter 1 or 2), the main indoor station will show the real number, while indoor extension will only show main doorphone in call log. (in order to compatible with the old version indoor extension)



- e. Main indoor station doesn't support switching IPC when video intercom with door station, but indoor extension support. (Unblockable for compatibility with old versions)

6 Series Indoor Station for CVBS Door Bell Firmware V2.1.56_build220815 Release Note (2022-08-30)

Device Model	DS-KH6320-TDE1, DS-KH6320-WTDE1, DS-KIS302-P
Firmware Version	V2.1.56_build220815
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

Modified Features

- f. Solve the defect of "when talking between mobile APP and cvbs doorbell (DS-KB2411T, DS-KB2421T), the doorbell can't hear the voice of APP".

6 Series Indoor Station for CVBS Door Bell Firmware V2.1.42_build220615 Release Note (2022-06-24)

Device Model	DS-KH6320-TDE1, DS-KH6320-WTDE1, DS-KIS302-P
Firmware Version	V2.1.42_build220615
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

Fix

1. Fixed the occasional issue that the status will not be changed after clicking 'Next' on Hik-Connect configuration in Activation wizard.
2. Fix the translation error of "Enter Answer" in the security question of Arabic wizard.
3. Fix the issue that the network parameters cannot be configured with an IP address of 0.0.0.0.
4. Fix the issue that the call record will be emptied occasionally.

6 Series Indoor Stations for CVBS Door Bell Firmware V2.1.42_build220606 Release Note (2022-06-06)

Device Model	DS-KH6320-TDE1, DS-KH6320-WTDE1, DS-KIS302-P
Firmware Version	V2.1.42_build220606
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

New

1. This new version is based on the device model: KH6320-TE1/WTE1. And the basic functions are consistent with KH6320-TE1/WTE1.

2. This is a new model of CVBS Indoor station support to connect Four-wire doorbells (KB2411、KB2421) as a secondary confirmation door station. Support intercom, preview, and opening the door.

3. Support forwarding to Hik-Connect when receiving a four-wire doorbell call.

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.