2019-1048 page 1 of 7

No: 2019-1048





TEST

REPORT

Equipment under Test: Network camera

Model Number: DS-2XM6425G0/F-L32

Manufacturer: Hangzhou Hikvision Digital Technology Co., Ltd

National Computer Peripheral Equipment Quality
Supervising Test Center

National Computer Peripheral Equipment Quality Supervising Test Center

Test Report

No:2019-1048

N <u>o</u> :2019-1048					
	N. A.	Model type	DS-2XM6425G0/F-L32		
Product	Network camera	Trademark	HIKVISION		
Entrusted By	Hangzhou Hikvision Digital Technology Co., Ltd	Testing Type	Entrustment		
Manufacturer	Hangzhou Hikvision Digital Technology Co., Ltd	Sample Class			
Sample Origin	Delivered	Delivery Date	2019-01-18		
Sample Number	One set	Delivered by	Su Weijie		
Sample Radix		Manufacture Date			
Test Standards	IEC 60529: 2013 Degrees of protection provided by enclosures(IP Code)				
Test Items	1#: IP Code 67 test of protection				
Test Result	This test proved that the manufactured by Hangzhou Hike the Test Standard.	vision Digital Tech			
Remark					

Approved by: John Checked by: John Chief tester: 3400

178m

Test Site	Nation	National Computer Peripheral Equipment Quality Supervising Test Center						
Test Date	2019-0	2019-01-21~01-23						
	S/N	Description	Model	No.	Cal due			
	1	Water jet hose nozzle	HY-IPX1-6	SB116	2019-04-19			
Main Testing Equipments and Instruments	2	Dust Chamber	SC-500	HJ0083	2019-04-09			
in su sin sin s								
Sample Number	1#: C1:	2345678						
Distribution Of Sample	1#: IP(Code 67 test of protection						
Remark	Ambier	c conditions: It temperature: 25°C humidity: 55% heric pressure: 101.2kPa						

Test Items	Technical specifications	
rest iteme		
IP6X	Dust-tight, No ingress of dust. The test is performed using a dust chamber. The talcum powder used shall be able to pass through a square-meshed sieve the nominal wire diameter of which is 50 µm and the nominal width of a gap between wires 75 µm. The amount of talcum powder to be used is 2 kg per cubic metre of the test chamber volume. Duration of test: 8 hours. After the test, the inside of EUT should be no dust.	
IPX7	Diving tests for a short time, No ingress of water. -The test is made using a water tank. -Temperature of the water tank: 20°C -Samples from the bottom of the water: 1000mm -Duration of test: 30 minutes After test, the inside of EUT should be no water.	Pass
Remark		

Tester: Wang Jue Shen Jianjun





EUT picture





Lens

Model: DS-2XM6425G0/F-L32





Material code: 311306942

Date: 01/2019 Lot Number: 21605528 2008021825/30

XXXXXXXXXXXXXX





DS-2XM6425G0/F-L32

C12345678

01/2019

Test picture



During the test (IP6X)



During the test (IPX7)

NOTES

- 1. Reports with no signet of "test report" or that of the inspect institute are all invalid.
- 2. Partial copy of this report is forbidden. Entire copy of the report without signet is invalid.
- 3. Report with no approval are invalid.
- 4. Altered report is invalid.
- 5. If any disagreement on this report, a written claim is requested to be submit to the institute within 15days on receipt of the report.
- 6. Generally, authorized inspection is only responsible for the samples inspected.

Address: 316#, Jiang Hong South Road, Hangzhou, China

Tel: +86 571 88278723 +86 571 88828284

Fax: +86 571 88366821

P.O.Box: 1215#, Hangzhou, China

Zip Code: 310052 E-mail: wangwx@ksign.cn WEB: www.ksign.cn

